

VEHICLE CONDITION REPORT

VIN	██████████	Seats	5	Fuel Type	Benzin
Year	2008	Body Type / Doors	Stufenheck/4	Turbo / Supercharged:	NA
Make	SUBARU	Exterior Colour	Blau	Eng. Cyl. / Arrange	4/Boxer
Model	Impreza	Paint Category		Engine Displacement	1994
Series	Impreza WRX STI / 265	Drive / Gears / Trans	Allrad permanent / 6/Schaltgetriebe	Interior Colour	Schwarz
Odometer	101025	Maintenance	1	Maintenance Date	14/06/2003
Licence Plate	██████████	Company Name	██████████	Inspection Loc.	██████████
Parking Bay		Address		Address	
Arrival Date	18/03/2022 16:23:39	City		City	
		State / Province, Zip		State / Province, Zip	
		Phone #		Phone #	
Inspector No.	██████████	Assgn. Date		CR Post Date	
Registration Date	01/06/2008	Insp. Date	18/03/2022 16:23:39	Print Date	

ACCESSORIES

ABS	Air-Conditioning	All Wheel Drive (4 X 4)	Alloy wheels	Central Locking System
Metallic	Navigation System	On-board Computer	Power Steering	Power Windows

TYRES

Position	Tread	Manufacturer	Diameter	Actual Size	Tyre Season
Front Left	2 mm	Unknown	17	225/45	Summer
Front Right	2 mm	Unknown	17	225/45	Summer
Rear Left	2 mm	Unknown	17	225/45	Summer
Rear Right	2 mm	Unknown	17	225/45	Summer

EXCEPTION / DAMAGE

Ref	Part	Type	Severity	Repair Mode	Cause	Paint Labour Cost	Repair Labour Cost	Labour Cost	Parts Cost	Net Cost	Dep.(%)	Dep. Amt.	Total Cost
1	Side Panel - Left Rear(Right)	Rusty	>8cm - 10cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
2	Rocker Panel - Right Rear	Bent	>6cm - 8cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
3	Rocker Panel - Left Rear	Rusty	>4cm - 6cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
4	Fender / Wing - Right Front	Rusty	>4cm - 6cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
5	Fender / Wing - Right Front	Scratched	>3cm - 4cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
6	Bumper - Front(Right)	Scuffed	>6cm - 8cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
7	Front Spoiler - Front	Scuffed	>8cm - 10cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
8	Hood / Bonnet - Front	Stone/Paint Chipped	>3cm - 4cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
9	Headlamp - Right Front(Right)	Other - See Notation	Other - See Notation	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
10	Headlamp - Left Front(Left)	Other - See Notation	Other - See Notation	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
11	Carrisserie - Technical(Left)	Stone/Paint Chipped	>1cm - 2cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
12	Fender / Wing - Left Front	Dented, No Pnt Dmg	>2cm - 3cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
13	Door - Left Front	Dented, No Pnt Dmg	>1cm - 2cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
14	Door - Left Rear	Dented, No Pnt Dmg	>1cm - 2cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
15	Side Panel - Left Rear(Right)	Stone/Paint Chipped	>3cm - 4cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
16	Boot Lid - Rear	Dented w/ Paint Dmg	>1cm - 2cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
17	Bumper - Rear(Right)	Scuffed	>2cm - 3cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
18	Door - Right Rear(Right)	Dented, No Pnt Dmg	>1cm - 2cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
19	Aluminium rim - Right Rear(Right)	Scuffed	>8cm - 10cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
20	Aluminium rim - Left Rear(Left)	Scuffed	>8cm - 10cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
21	Aluminium rim - Left Front	Scuffed	>6cm - 8cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
22	Protection Strip - Right Rear	Scuffed	>4cm - 6cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
23	Rocker Panel - Right Front(Left)	Dented, No Pnt Dmg	>2cm - 3cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
24	Trim-Cover - Rear	Loose	Other - See Notation	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
25	Seat - Left Front	Rusty	>2cm - 3cm	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
26	Door Handle - Left Front(Left)	Missing	Replace	RR	SV	€ 0.00	€ 9.00	€ 9.00	€ 11.37	€ 20.37	0.00%	€ 0.00	€ 20.37
27	Seat - Right Front	Rusty	Other - See Notation	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
28	Dash Panel - Forward	Missing	Other - See Notation	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	0.00%	€ 0.00	€ 0.00
29	Circuit de freinage - Technical	Stone/Paint Chipped	Other - See Notation	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
30	Tail Lamp - Right Rear	Other - See Notation	Other - See Notation	NA	SV	€ 0.00	€ 0.00	€ 0.00	€ 0.00	€ 0.00	55.00%	€ 0.00	€ 0.00
Total						€ 0.00	€ 9.00	€ 9.00	€ 11.37	€ 20.37		€ 0.00	€ 20.37

Comments

Ref	Comments
9	milchig
10	milchig

Am Fahrzeug wurde eine Lackschichtmessung vorgenommen und die Werte lagen innerhalb der Toleranz. Eine Nachlackierung des Fahrzeuges kann auf Grund des Alters aber nicht ausgeschlossen werden. Der bei der HU-Untersuchen fehlende DB-Eater wurde nachträglich verbaut. Eine Unterbodenkontrolle konnte auf Grund der Standortbedingungen nicht durchgeführt werden.

Labour Cost Summary

Type	Hourly Rate	Number of Hours	Labour Cost
Frame	€ 95.00	0	€ 0.00
Mechanical	€ 90.00	0.10	€ 9.00
Metal	€ 95.00	0	€ 0.00
Paint	€ 100.00	0	€ 0.00
Total		0.10	€ 9.00

Miscellaneous

Inspection Checklist

No Odometer Tampered : No

Smoker : No

Vehicle Not Driveable : No

DOCUMENT LIST

Present Missing

Anti-Theft Code	<input checked="" type="checkbox"/>	Audio Manual	<input type="checkbox"/>
Card Key	<input type="checkbox"/>	Certificate of Conformity	<input checked="" type="checkbox"/>
Delivery Condition Report	<input type="checkbox"/>	EV Cable	<input checked="" type="checkbox"/>
Emmissions Cert	<input checked="" type="checkbox"/>	Euro Sticker	<input checked="" type="checkbox"/>
Insurance	<input checked="" type="checkbox"/>	Original Key	<input checked="" type="checkbox"/>
Owners Manual	<input type="checkbox"/>	Radio Code	<input checked="" type="checkbox"/>
Registration Form	<input checked="" type="checkbox"/>	Remote Entry Key	<input checked="" type="checkbox"/>
Service Manual	<input type="checkbox"/>	Spare Key	<input checked="" type="checkbox"/>
Tax Sticker	<input checked="" type="checkbox"/>	Transport Licence	<input checked="" type="checkbox"/>



 Standard	 Standard	 Standard	 Standard	 Standard
 Standard	 Standard	 Standard	 Standard	 Standard
 Standard	 Standard	 Standard	 Standard	 Standard
 Standard	 Standard	 Standard	 Standard	 Standard
 Standard	 Standard	 Standard	 Standard	 Standard
 Standard	 Standard	 Standard	 Standard	 Standard
 Standard	 Standard	 Standard	 Standard	 Standard
 Standard	 Standard	 Standard	 Standard	 Standard
 Standard	 Standard	 Standard	 Standard	 Standard
 Ref 1 ;	 Ref 1 ;	 Ref 1 ;	 Ref 1 ;	 Ref 24 ;
 Ref 24 ;	 Ref 2 ; 3 ;	 Ref 2 ; 3 ;	 Ref 2 ; 3 ;	 Ref 2 ; 3 ;



Ref 2 ; 3 ;



Ref 4 ;



Ref 4 ;



Ref 5 ;



Ref 5 ;



Ref 5 ;



Ref 5 ;



Ref 6 ;



Ref 6 ;



Ref 6 ;



Ref 6 ;



Ref 6 ;



Ref 7 ;




Ref 8 ;



Ref 8 ;



Ref 8 ;



Ref 8 ;



Ref 9 ;



Ref 9 ;



Ref 10 ;



Ref 11 ;



Ref 11 ;



Ref 12 ;




Ref 12 ;



Ref 12 ;



Ref 13 ;



Ref 13 ;



Ref 14 ;



Ref 14 ;



Ref 15 ;



Ref 15 ;



Ref 16 ;



Ref 16 ;



Ref 17 ;




Ref 17 ;




Ref 30 ;



Ref 30 ;



Ref 18 ;



Ref 18 ;



Ref 19 ;



Ref 19 ;



Ref 19 ;



Ref 19 ;



Ref 19 ;



Ref 19 ;



Ref 20 ;



Ref 20 ;



Ref 20 ;



Ref 21 ;



Ref 21 ;




Ref 21 ;



Ref 29 ;




Ref 29 ;



Ref 29 ;



Ref 29 ;



Ref 21 ;



Ref 29 ;



Ref 29 ;



Ref 29 ;



Ref 29 ;



Ref 29 ;



Ref 29 ;



Ref 29 ;



Ref 29 ;



Ref 29 ;



Ref 25 ;



Ref 25 ;



Ref 25 ;



Ref 26 ;



Ref 26 ;



Ref 22 ;



Ref 22 ;



Ref 23 ;



Ref 23 ;



Ref 27 ;



Ref 27 ;



Ref 27 ;



Ref 28 ;